

**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06**

Site Name: Longview Refining

CERCLIS ID#: ~~TX0000605387~~

Alias Site Names:

Address:

601 Premier Road

City/County or Parish/State/Zip Code:

Longview, Gregg County, TX

Report Type, Date, and Author:

Preliminary Assessment, April 2000, TNRCC

RECOMMENDATION:

☐ 1. No Further Remedial Action Planned under Superfund (NFRAP)

☒ 2. Further Investigation Needed Under Superfund

☐ PA ☐ HRS ☒ SSI ☐ RA ☐ ESI ☐ RI/FS ☐ SI

To be performed by:

Other:

Priority: ● High ○ Low

3. Action Deferred ☐ RCRA ☐ NRC

NOTIFY AUTHORITY:

☐ Removal

☐ SMCRA

☐ NRC

☐ UIC

☐ RCRA

☐ Remedial

☐ Resource Trustee

☐ SPCC

☐ TSCA

☒ State/Tribe

☐ CERCLA Enforcement

☐ Other

☐ CAA

☐ NPDES

☐ Federal Facility

SEND SSSR COPIES TO:

☐ 6SF-AC

☐ 6WQ-SP

☐ ATSDR

☒ State Agency ☐ Tribal Agency

DISCUSSION:

Longview Refining Associates, Inc. (LRA) is a petroleum refinery covering 34 acres and containing fifty above ground storage tanks, six surface impoundments and a variety of process equipment including cooling towers, coalescers, heat exchangers, boilers and compressors. The refinery was constructed in 1939 and operated under a variety of owners until it was closed down in 1982 under the ownership of Crystal Oil Company. LRA purchased the refinery in 1989 and began operations in 1990. The refinery was closed down for the final time in 1992.

There are residential properties along the east side of the refinery within 200 feet of the LRA property boundary. Swinging Bridge Creek, a perennial stream flows through the property and received storm water discharges through three permitted outfalls. There is past documentation of contaminants entering the creek through the outfalls. Additional areas of concern (AOC) at the facility include soil contamination, unlined surface impoundments, and above ground storage tanks which could impact both the surface water and ground water pathways. Based on the available information at this time, it is recommended that a Screening Site Inspection be conducted at this site to further evaluate both the surface water and ground water pathways.

APPROVALS:

Report Reviewed by:

William

Rhotenberry/R6/USEPA/US

(Site Assessment Manager 6SF-RA)

for Philyp
● Approved ○ Disapproved

09/20/2001

942546



Disposition Recommended by:

Blak for Susan Wilkes 7/24/01

☒ Approved

☐ Disapproved

(Team Leader 6SF-RA)